

ONE YEAR LIMITED WARRANTY

Dear Homebuyer(s):

Congratulations on Your purchase of a Summertree Home with this express One Year Limited Warranty protection. This Warranty Booklet contains Your One Year Limited Warranty. Congratulations and enjoy Your new Summertree Home!

DEFINITIONS: **You and Your** means the person(s) who holds title to the Home. **Home** means the dwelling and garage. **Builder** means Summertree Homes, Inc. **Effective Date of Warranty** is the earliest of Your closing date, first title transfer, or the date You or anyone else first occupied the Home, if that was before closing. **Limited Warranty** means the express warranty described by the terms and provisions contained within this Warranty Booklet. **Warranty Term** is the period during which a warranted defect must first occur in order to be covered hereunder, and is that period which begins on the Effective Date of Warranty as defined above, and ends one year later. **Defect** is defined in each instance as a failure to meet the Construction Performance Guidelines for workmanship and systems as set forth in this Agreement. **Structural Defect** is defined as actual physical damage to the designated load-bearing elements of the Home caused by failure of such load-bearing elements which affects their load-bearing functions to the extent that Your Home becomes unsafe, unsanitary, or otherwise unlivable. This is coverage for catastrophic failure of load-bearing elements of Your Home. The designated load-bearing elements that are covered under this Structural Defect warranty are:

1. Footings and Foundation systems;
2. Beams;
3. Girders;
4. Lintels;
5. Columns;
6. Walls and partitions;
7. Roof framing systems; and
8. Floor Systems.

Examples of elements not covered by this Structural Defect Warranty which are deemed NOT to have Structural Defect potential are:

1. Non-load-bearing partitions and walls;
2. Wall tile or paper, etc.;



3. Plaster, laths, or drywall;
4. Flooring and sub-flooring material;
5. Brick, stucco, stone or veneer;
6. Any type of exterior siding;
7. Roof shingles, roof tiles, sheathing, and tar paper;
8. Heating, cooling, ventilating, plumbing, electrical and mechanical systems;
9. Appliances, fixtures or items of equipment
10. Doors, trim, cabinets, hardware, insulation, paint, stains; and
11. Basement and other interior floating, ground-supported concrete slabs.

WHAT TO DO IN THE CASE OF AN EMERGENCY: An emergency is a condition that if not immediately repaired may cause danger to the Home or its occupants. You must contact Summertree Homes, Inc. immediately. If You are unable to contact Summertree Homes, Inc. for emergency authorization, 1) You must make minimal repairs until authorization for more extensive repairs has been approved by Summertree Homes, Inc., 2) You must take action in order that further damage can be mitigated, and 3) You must report the emergency to Summertree Homes, Inc. on the next business day.

MEDIATION: In the event Purchaser and Seller are unable to resolve any dispute, prior to arbitration, the parties shall select a mutually acceptable mediator to assist with resolution of such dispute. If the parties are unable to agree upon a mediator, each party shall designate a representative. The two representatives shall mutually agree upon the selection of a mediator. Both parties agree to be bound by the mediator's decisions. The mediator's fee shall be split equally by both parties.

ARBITRATION: If the parties are unable to resolve their dispute after mediation, then either party may file a Demand for Arbitration. Any dispute between Purchaser and Seller shall be submitted to arbitration to be conducted in accordance with the New Mexico Uniform Arbitration Act. Arbitration shall be initiated by filing a written Demand for Arbitration with the other party at the address set forth herein. Within 30 days of the submission of the written Demand for Arbitration, Purchaser and Seller shall mutually agree upon a single arbitrator. If the parties are unable to agree upon an arbitrator, the presiding Judge of the Second Judicial District Court in Bernalillo County shall appoint an arbitrator. The arbitration shall take place in the Home of the purchaser, unless the parties mutually agree to another location. Only compensatory damages are recoverable, and the arbitrator shall have no authority to award punitive damages or damages for emotional distress or consequential damages. In any event, neither party shall be liable to the other for an amount in excess of the original purchase price of the house. Each party shall bear its own attorney fees and costs. The costs incurred by the arbitrator shall be split equally between the parties unless the arbitrator decides otherwise. The award rendered by the arbitrator shall include a written decision that includes findings of fact and conclusions of law. The award by the arbitrator shall be final, non-appealable and any judgment on the award rendered by the arbitrator may be entered in any court of competent jurisdiction. **NOTICE:** Neither the Contractor's License Bond nor the License issued under 60-13-19 of the Construction Industries Licensing Act protects the consumer if the contractor defaults on this contract.

ATTORNEY'S FEES: In the event of a dispute, each party agrees to pay their own Attorney's fees.

WARRANTIES TRANSFERABLE: All of Your rights and obligations hereunder shall fully transfer, up to the remaining amount of the Warranty Limit, to each successor in title to the Home, including any mortgagee in possession, for the remainder of the One Year Limited Warranty Term and any such transfer shall in no way affect or reduce the coverage under this One Year Limited Warranty for its unexpired term. There is no limit to the number of such transfers during the One Year Limited Warranty Term, nor any cost hereunder as a result of such successions. If You sell Your Home during the One Year Limited Warranty Term, You agree to give this One Year Limited Warranty to Your buyer, to inform Your buyer of warranty rights and to make it possible for the buyer to fulfill the obligations under the terms of this One Year Limited Warranty. If You are a successor owner of the Home (that is, an owner other than the original purchaser), Your Home will benefit from the coverage provided by this express One Year Limited Warranty. Likewise, You are also bound by all the terms and conditions of the One Year Limited Warranty including but not limited to, claims procedures and participation in arbitration.

YOUR OBLIGATIONS: The Warranty coverage pays for the cost of labor and materials to correct a covered Defect or Structural Defect. Your obligation is to care for Your Home in such a way as to prevent or minimize damage to it. You should be aware that all new Homes go through a period of settlement and movement. During this period, Your Home may experience some minor material shrinkage, cracking and other events which are normal and customary. Remember that You are responsible for proper maintenance of Your Home including maintaining Builder-set grades around the Home, planting trees and shrubs at the proper distance, and conforming to generally accepted landscape practices for Your region.

EXCLUSIONS: This One Year Limited Warranty does not provide any coverage for the following items, which are specifically excluded.

1. Damage to land and other real property that was not part of Your Home, or any property that was not included in the Summertree Homes, Inc. purchase agreement and all addendums to the purchase agreement.
2. Damage to swimming pools and other recreational facilities; driveways; boundary walls, retaining walls and bulkheads (except where boundary walls, retaining walls and bulkheads are necessary for the structural stability of the Home); fences; landscaping (including sodding, seeding, shrubs, trees, plantings); sprinkler systems, patios, decks, stoops, steps and porches, outbuildings, detached carports, or any other appurtenant structure or attachment to the dwelling; or other additions or improvements not a part of Your Home;
3. Loss or damage which arises while Your Home is being used primarily for nonresidential purposes;
4. Changes in the level of underground water table which were not reasonably

- foreseeable at the time of construction of Your Home;
5. Any condition which has not resulted in actual physical damage to Your Home.
 6. Any loss or damage that is caused or made worse by any of the following causes, whether acting alone or in sequence or concurrence with any other cause or causes whatsoever, including without limitation:
 - a. Negligence, improper maintenance, defective material or work supplied by, or improper operation by, anyone other than Summertree Homes, Inc. or its employees, agents or subcontractors including failure to comply with the warranty requirements of manufacturers of appliances, equipment or fixtures;
 - b. Change of the grading of the ground that does not comply with accepted grading practices, or failure to maintain the original grade;
 - c. Riot or civil commotion, war, vandalism, hurricane, tornado or other windstorm, fire, explosion, blasting, smoke, water escape, tidal wave, flood, hail, snow, ice storm, lightning, falling trees or other objects, aircraft, vehicles, mudslide, avalanche, earthquake, or volcanic eruption;
 - d. Abuse or use of Your Home, or any part thereof, beyond the reasonable capacity of such part for such use;
 - e. Microorganisms, fungus, decay, wet rot, dry rot, soft rot, rotting of any kind, mold, mildew, vermin, termites, insects, rodents, birds, wild or domestic animals, plants, corrosion, rust, radon, radiation, formaldehyde, asbestos, any solid, liquid or gaseous pollutant, contaminant, toxin, irritant or carcinogenic substance, whether organic or inorganic, and electromagnetic field or emission, including any claim of health risk or uninhabitability based on any of the foregoing;
 - f. Your failure to minimize or mitigate any defect, condition, loss or damage as soon as practicable;
 9. Any loss or damage caused by buried debris, underground springs, sinkholes, mineshafts or other anomalies which were not reasonably foreseeable in a building site provided by You;
 10. Any request for warranty performance submitted to Summertree Homes, Inc. after an unreasonable delay or after the expiration of the applicable One Year Limited Warranty Term;
 11. Loss caused, in whole or in part, by a peril or occurrence for which compensation is provided by state legislation or public funds;
 12. Costs of shelter, transportation, food, moving, storage, or other incidental expenses related to relocation during repair, or any other costs due to loss of use, inconvenience, or annoyance;
 13. Diminished market value of Your Home; and
 14. Any and all consequential loss or damage, including without limitation, any damage to property not covered by this One Year Limited Warranty, any damage to personal property, any damage to property which You do not own, any bodily damage or personal injury of any kind, including physical

or mental pain and suffering and emotional distress, and any medical or hospital expenses or lost profits.

The One Year Limited Warranty does not apply to any manufactured item such as appliances, fixtures, equipment (except as specifically defined in the Construction Performance Guidelines) or any other item which is covered by manufacturer's warranty, nor does it cover systems Defects that are caused by failure of any such manufactured item. Appliances and items of equipment not covered by this One Year Limited Warranty, include but are not limited to: air conditioning units, attic fans, boilers, burglar alarms, carbon monoxide detectors, ceiling fans, central vacuum systems, chimes, dishwashers, dryers, electric meters, electronic air cleaners, exhaust fans, fire alarms, fire protections sprinkler systems, freezers, furnaces, garage door openers, garbage disposals, gas meters, gas or electric grills, heat exchangers, heat pumps, humidifiers, intercom, oil tanks, outside lights or motion lights not attached to the Home, range hoods, ranges, refrigerators, sewage pumps, smoke detectors, solar collectors, space heaters, sump pumps, thermostats, trash compactors, washers, water pumps, water softeners, water heaters, whirlpool baths, and whole house fans.

CONSTRUCTION PERFORMANCE GUIDELINES: The following Construction Performance Guidelines are standards that have been developed and accepted by the residential construction industry in general. While it is virtually impossible to develop Construction Performance Guidelines for each possible deficiency, Summertree Homes, Inc. has attempted to isolate the most common actual physical damage deficiencies that occur in Your Home. The following Construction Performance Guidelines are expressed in terms of required standards that Summertree Homes, Inc. construction should meet. Noncompliance with these construction standards calls for corrective action by Summertree Homes, Inc. Summertree Homes, Inc. will try to its best ability to match and replace with Your original choice of colors and material, except where You custom ordered the items. Summertree Homes, Inc. cannot be responsible for discontinued items, changes in dye lots, colors or patterns, or items ordered outside of the original construction. Normal wear and deterioration; failure of Summertree Homes, Inc. to perform any washing, cleaning, or cleanup, are not covered under the One Year Limited Warranty.

CONSTRUCTION PERFORMANCE GUIDELINES

INDEX

	<u>PAGE</u>
1. Site Work	1
1.1 Grading	1
1.2 Drainage	1
2. Foundation and Concrete	1
2.1 Cast-In Place Concrete	1
2.2 Construction Control Joints	2
3. Masonry	3
3.1 Unit Masonry (Brick, Block, and Stone)	3
3.2 Stucco and Cement Plaster	3
4. Carpentry and Framing	3
4.1 Plywood and Joists	3
4.2 Finish Carpentry	4
5. Thermal and Moisture Protection	5
5.1 Waterproofing	5
5.2 Insulation	5
5.3 Ventilation and Moisture Control	6
5.4 Sealants	6
5.5 Exterior Siding	6
5.6 Roofing	7
5.7 Sheet Metal	7
6. Doors and Windows	8
6.1 Doors: Interior and Exterior	8
6.2 Garage Doors (attached garage)	8
6.3 Wood, Plastic, and Metal Windows	8
6.4 Hardware	9
6.5 Storm Doors, Windows and Screens	9
6.6 Weatherstripping and Seals	9
6.7 Glass and Glazing	9
7. Finishes	9
7.1 Lath and Plaster	9
7.2 Drywall	10
7.3 Hard Surfaces	10
7.4 Resilient Flooring	10
7.5 Finished Wood Flooring	11
7.6 Painting	11
7.7 Wall Covering	12
7.8 Carpeting	13
8. Specialties	13
8.1 Fireplaces	13
9. Cabinets and Vanities	14
9.1 Kitchen Cabinets and Vanities	14
9.2 Countertops	14
10. Mechanical	14
10.1 Plumbing	14
10.2 Water Supply	14
10.3 Heating and Air Conditioning	15
11. Electrical Components	16
11.1 Switches and Receptacles	16
11.2 Service and Distribution	16

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
------------	-------------------------------------	----------------------------------	-----------

1. Site Work

1.1 Grading

Settling of ground around foundation, utility trenches or other areas on the property where excavation and backfill have taken place that affect drainage away from Home.

Settling of ground around foundation walls, utility trenches or other filled areas that exceeds a maximum of six inches from finished grade established by Builder

If Builder has provided final grading, Builder shall fill settled areas affecting proper drainage, one time only, during the first year Warranty Term. You are responsible for removal and replacement of shrubs and other landscaping affected by placement

1.2 Drainage

Improper Surface Drainage.

Necessary grades and swales shall be established to provide proper drainage away from the Home. Site drainage, under the Limited Warranty, is limited to grades within 10-feet and swales within 20-feet of the foundation of the Homes. Standing or ponding water shall not remain in these areas for a periods longer than 24-hours after a rain, except in swales that drain from adjoining properties or where a sump pump discharges in these areas an extended period of 48-hours is to be allowed for water to dissipate. The Possibility of standing water after an unusually heavy rainfall should be anticipated and is not to be considered a deficiency. No grading determination is to be made while there is frost or snow or when the ground is saturated.

Builder is only responsible for initially establishing the proper grades, swales and drainage away from the Home. You are responsible for maintaining such grades and swales once constructed by the Builder. Builder is not responsible for drainage deficiencies attributable to grading requirements imposed by state, county, or local governing agencies.

Standing or ponding water outside of defined swales and beyond 10-feet from the foundation of the Home, or that is within 10-feet but is caused by unusual grade conditions, or retention of treed areas, is not considered a deficiency. Standing or ponding water caused by changes in the grade or placement of sod, fencing, or any other obstructions by You are excluded from Limited Warranty coverage.

Soil Erosion

NONE. NO COVERAGE.

NONE. Builder is not responsible for soil erosion due to acts of God or other conditions beyond the Builder's control.

Soil erosion and runoff caused by failure of You to maintain the properly established grades, drainage structures and swales; stabilized soil, sodded, seeded and landscaped areas; are excluded from Limited Warranty coverage.

Grassed or landscaped areas, which are disturbed or damaged due to work performed by Builder on the property in correcting a deficiency.

Landscaped areas that are disturbed during repair work are deficiencies.

Restore grades, seed and landscape to meet original condition. Builder is not responsible for grassed or landscaped areas which are damaged by others, including any work performed by public or private utility companies.

Replacement of trees and large bushes that existed at the time Home was constructed or those added by You after occupancy or those that subsequently die are excluded from Limited Warranty coverage.

2. Foundation and Concrete

2.1 Cast-In Place Concrete

Basement or foundation wall cracks, other than expansion or control joints.

Concrete cracks greater than 1/4-inch in width, or which allow exterior water to leak into basement, are deficiencies.

Repair non-structural cracks by surface patching. These repairs should be made toward the end of the first year of Limited Warranty coverage to permit normal stabilizing of the Home by settling.

Shrinkage Cracks are not unusual and are inherent in the concrete curing process.

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
Cracking of Basement floor.	Minor cracks in concrete basement floors are common. Cracks exceeding 1/4-inch in width or 3/16-inch in vertical displacement are deficiencies.	Repair cracks exceeding maximum tolerance by surface patching or other methods, as required.	
Cracking of attached garage floor slab.	Cracks in concrete garage floor greater than 3/16-inch in width or 3/16-inch in vertical displacement are deficiencies.	Builder shall repair excessive cracks in the slab by filling, chipping out and surface patching, or other suitable method to meet the Construction Performance Guideline. Repaired area may not match the existing floor in color and texture.	Builder is not responsible for cracking or deterioration caused by the storage of unusually heavy equipment or placement of excessive loads that exceed the weight of a typical automobile or lights truck, or by other factors beyond the Builder's control. Movement and the resulting cracking may be minimized by good drainage, proper installation of landscaping and suitable maintenance.
Cracks in attached patio slab and sidewalks.	NONE. NO COVERAGE.	NONE.	NO COVERAGE is provided for this element under the Limited Warranty.
Cracks in concrete slab-on-grade floors, with finish flooring.	Cracks that rupture or significantly impair the appearance or performance of the finish flooring material are deficiencies.	Repair cracks as required so as not to be apparent when the finish flooring material is in place. Repair or replace finish flooring.	
Uneven concrete floor slabs.	Except for basement floors or where a floor or a portion of floor has been designed for specific drainage purposes, concrete floors in rooms finished for habitability by Builder shall not have pits, depressions or area or unevenness exceeding 3/8-inch in 32-inches.	Repair/replace to meet the Construction Performance Guidelines. Where applicable, surface patching is an accepted method of repair. Reinstall or replace any finish flooring material as necessary.	
Interior concrete work is pitting, scaling, or spalling.	Interior concrete surfaces that disintegrate to the extent that aggregate is exposed and loosened under normal conditions of use are deficiencies.	Builder shall take whatever corrective action is necessary to repair or replace defective concrete surfaces.	Builder is not responsible for deterioration caused by salt, chemical, mechanical implements, or other factors beyond the Builder's control.
Efflorescence is present on surface of basement floor.	NONE. NO COVERAGE.	NONE. This is a normal condition.	
Separation of brick or masonry edging from concrete slab or step.	It is common for the joint to crack between concrete and masonry due to the dissimilarity of the materials. Cracks in excess of 1/4-inch are a deficiency.	Grout crack fully and reset loose masonry where required. Replacement of masonry material, if required, shall match the existing as closely as possible.	
Cracking, Settling or heaving of stoops and steps.	Stoops and steps that have settled, heaved, or separated in excess of 1-inch from Home are a deficiency	Builder will make a reasonable and cost effective effort to meet the Construction Performance Guideline.	

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
<p><i>2.2 Construction and Control Joints</i> Separation or movement of concrete slabs within the structure at construction and control joints.</p>	NONE. NO COVERAGE.	NONE.	Concrete Slabs within the structure are designed to move at construction and control joints and are not deficiencies. You are responsible for maintenance of joint material.
3. Masonry			
<i>3.1 Unit Masonry (Brick, Block and Stone)</i>			
Cracks in masonry, brick, or stone veneer	Small Hairline cracks resulting from shrinkage are common in mortar joints of masonry construction. Cracks greater than 1/4-inch in width or are visible from a distance in excess of 20-feet are deficiencies.	Builder will repair cracks that exceed 1/4-inch by tuck pointing and patching. These repairs should be made toward the end of the first year of Limited Warranty coverage to permit Home to stabilize and normal settlement to occur. Builder is not responsible for color variations between existing and new mortar.	
Cracks in concrete block basement walls.	Small shrinkage cracks that do not affect the structural ability of masonry foundation walls are not unusual. Cracks 1/4-inch or greater in width are deficiencies.	Builder shall investigate to determine cause. Builder shall take the necessary steps to remove the cause and make repairs by pointing and patching, reinforcement or replacement of the defective courses.	
Concrete block basement wall is bowed.	Block concrete walls shall not bow in excess of 1-inch in 8 feet when measured from the base to the top of the wall.	Builder shall repair basement walls that are bowed in excess of 1-inch in 8 feet.	
<i>3.2 Stucco and Cement Plaster</i>			
Cracking or spalling of stucco and cement plaster.	Hairline cracks in the stucco or cement plaster are common especially if applied directly to masonry back-up. Cracks greater than 1/8-inch in width or spalling of the finish surfaces are deficiencies.	Scrape out cracks and spalled areas, one time only during the first warranty term. Fill with cement plaster or stucco to match finish and color as close as possible.	Builder is not responsible for failure to match color or texture, due to nature of material.
Separation of coating from base on exterior stucco wall.	The coating shall not separate from the base on an exterior stucco wall.	Builder shall repair areas where the coating has separated from the base.	Builder is not responsible for failure to match color or texture, due to the nature of the material.
4. Carpentry and Framing			
<i>4.1 Plywood and Joists</i>			
	Loud and objectionable squeaks caused by improper installation or loose sub floor are deficiencies, but a totally squeak-proof floor cannot be guaranteed.	Builder will refasten any loose sub floor or take other corrective action to reduce squeaking to the extent possible within reasonable repair capability without removing floor and ceiling finishes.	Floor squeaks may occur when a sub floor that has come loose from the joists is deflected by the weight of a person and rubs against the nails that hold it in place. Squeaks may also occur when one joist is deflected while the other members remain stationary. Because the Construction Performance Guidelines requires the Builder to make a reasonable attempt to eliminate squeaks without requiring removal of floor and ceiling finishes, nailing loose sub flooring with casing nails into the carpet surface and countersinking the head is an acceptable practice.

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
Uneven wood framed floors.	Wood floors shall not have more than a 1/4-inch ridge or depression within any 32-inch measurement.	Correct or repair to meet the Construction Performance Guidelines.	
Bowed walls or ceilings.	All interior and exterior frame walls or ceilings have slight variations on the finish surfaces. Walls or ceilings that are bowed more than 1/2-inch within a 32-inch horizontal measurement; or 1/2-inch within any 8 foot vertical measurement, are deficiencies.	Exterior and interior framed walls or ceilings bowed in excess of the allowable standard shall be corrected to meet the allowances of the Construction Performance Guidelines.	
Wood frame walls out of plumb.	Wood frame walls that are more than 3/8-inch out of plumb for any 32-inch vertical measurement are a deficiency.	Make necessary repairs to meet the Construction Performance Guidelines.	
Wood beam or post is split.	Beams or posts, especially those 2-1/2-inches or greater in thickness, will sometimes split as they dry subsequent to construction. Unfilled splits exceeding 1/4-inch in width and all splits exceeding 3/8-inch in width and more than 4 inches in length are deficiencies.	Builder shall repair or replace as required. Filling splits is acceptable for widths up to 3/8-inch.	Some characteristics of drying wood are beyond the control of the builder and cannot be prevented.
Exterior sheathing and sub flooring which delaminates or swells.	Sheathing and sub flooring delaminating or swelling on the side that the finish material has been applied is a deficiency.	Builder shall repair or replace sub flooring or sheathing as required. Replacement of the finish materials, when necessary, shall be done to match the existing finish as closely as possible.	
Wood floor is out of square.	The diagonal of a triangle with sides of 12-feet and 16-feet along the edges of the floor shall be 20-feet plus or minus 1/2-inch.	Builder shall make necessary modifications to any floor not complying with the Construction Performance Guidelines.	
<i>4.2 Finish Carpentry</i> Unsatisfactory quality of finished exterior trim and workmanship.	Joints between exterior trim elements and siding or masonry, which are in excess of 1/4-inch, are deficiencies. In all cases, the exterior trim abutting the masonry siding shall be capable of performing its function to exclude the elements.	Repair open joints and touch up finish coating where required to match existing as closely as possible. Caulk open joints between dissimilar materials.	
Unsatisfactory quality of finished interior trim and workmanship.	Joints between moldings and adjacent surfaces that exceed 1/8-inch in width are deficiencies.	Repair defective joints and touch up finish coating where required to match as closely as possible. Caulking is acceptable.	
Interior trim is split.	NONE. NO COVERAGE.	NONE.	Splits, cracks, and checking are inherent characteristics of all wood products, and are not considered deficiencies.

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
Hammer marks visible on interior trim.	Hammer marks on interior trim shall not be readily visible from a distance of 6-feet under normal lighting conditions.	Builder shall fill hammer marks and refinish or replace affected trim to meet the Construction Performance Guidelines. Refinished or replaced areas may not match surrounding areas exactly.	
Exposed nail heads in woodwork.	Settling nails and filling nail holes are considered part of painting and finishing. After painting or finishing, nails and nail holes shall not be readily visible from a distance of 6 feet under normal lighting conditions.	Fill nail holes where required and if necessary, touch up paint, stain, or varnish to match as closely as possible.	Nail holes do not have to be filled where the surface finish is not conducive or so designed to have nail holes filled because of the product. Nail holes in base and trim in unfinished rooms or closets do not have to be filled.
5. Thermal and Moisture Protection			
<i>5.1 Waterproofing</i>			
Leaks in basement or in foundation/crawl space.	Leaks resulting in actual trickling of water through the walls or seeping through the floor are deficiencies.	Take such action as is necessary to correct basement and crawl space leaks, except where the cause is determined to be the result of Your negligence. Where a sump pit has been installed by Builder in the affected area but the sump pump was not contracted for or installed by the Builder, no action is required until a properly sized pump is installed by You in an attempt to correct the condition. Should the condition continue to exist, then Builder shall take necessary action to correct the problem.	Leaks caused by landscaping improperly installed by You or failure by You to maintain proper grades are excluded from the Limited Warranty coverage. Dampness in basement and foundation walls or in concrete basement and crawl space floors is often common to new construction and is not a deficiency.
<i>5.2 Insulation</i>			
Insufficient Insulation.	Insulation that is not installed around all habitable areas in accordance with established local industry standards is a deficiency.	Builder shall install insulation of sufficient thickness and characteristics to meet the local industry standards. In the case of dispute, cost of investigating the sufficiency of insulation and restoring areas to prior condition is to be borne by You if it is found that the standard has been met by the Builder.	
Sound transmission between rooms, floor levels, adjoining condominium units in a building, or from the street into Home.	NONE. NO COVERAGE.	NONE.	NO COVERAGE is provided for soundproofing.

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
------------	-------------------------------------	----------------------------------	-----------

5.3 Ventilation and Moisture Control

Inadequate ventilation or moisture control in crawl spaces.	Crawl spaces shall have adequate ventilation to remove moisture or other approved method of moisture control. Ventilation or other moisture control methods shall be considered inadequate if there is damage to supporting members or insulation due to moisture accumulation.	Builder shall investigate to determine cause, and make necessary repairs. Corrective action may include the installation of properly sized louvers, vents, vapor barrier, or other locally approved method of moisture control.	Temporary conditions may cause condensation in crawl spaces that cannot be eliminated by ventilations and /or vapor barrier. Night air may cool foundation walls and provide a cool surface on which moisture may condense. In Homes that are left unheated in the winter, the underside of the floors may provide a cold surface on which warmer crawl space air may condense. These and other similar conditions are beyond the Builder's control. Maintaining adequate heat and seasonal adjustment of vents is Your responsibility.
Inadequate ventilation or moisture control in attics or roofs.	Attics or roofs shall have adequate ventilation to remove moisture, or other approved method of moisture control. Ventilation or other moisture control methods shall be considered inadequate if there is damage to supporting members or insulation due to moisture accumulation.	Builder shall investigate to determine cause, and make necessary repairs. Corrective action may include the installation of properly sized louvers, vents, vapor retarder, or other locally approved method of moisture control.	You are responsible for keeping existing vents unobstructed. Locally approved and properly constructed "hot roof" or other alternative roof designs may not require ventilation, and where there is no evidence of moisture damage to supporting members or insulation, are not deficiencies.
Attic vents or louvers leak.	Attic vents and Louvers shall not leak.	Builder shall repair or replace the roof vents as necessary to meet the Construction Performance Guidelines.	Infiltration of wind-driven rain and snow are not considered leaks and are beyond the control of the Builder.
Bath or kitchen exhaust fans improperly vented into attic.	Bath or kitchen exhaust fans that are vented into attics causing moisture to accumulate resulting in damage to supporting members or insulation, are deficiencies.	Builder shall vent exhaust fans to the outside to correct the deficiencies.	

5.4 Sealants

Water or air leaks in exterior walls due to inadequate caulking.	Joints and cracks in exterior wall surfaces and around openings that are not properly caulked to exclude the entry of water or excessive drafts are a deficiency.	Repair and/or caulk joints in exterior wall surfaces as required to correct the deficiency one time only during the first year of Limited Warranty coverage.	You must maintain caulking once the condition is corrected.
--	---	--	---

5.5 Exterior Siding

Delamination, Splitting, or Deterioration of exterior siding.	Exterior siding that delaminates, splits or deteriorates is a deficiency.	Repair/replace only the damaged siding. Siding to match the original as closely as possible, however, You should be aware that the new finish may not exactly match the original surface texture or color.	Delaminated siding due to Your actions or neglect, such as delamination caused by sprinkler system repeatedly wetting siding, is not a deficiency.
Loose or fallen siding.	All siding that is not installed properly, which causes some to come loose, or fall off, is a deficiency.	Reinstall or replace the siding and make it secure.	Loose or fallen siding due to Your actions or neglect, such as leaning heavy objects against the siding, impact, or sprinkler systems repeatedly wetting siding, is not a deficiency.

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
Siding is bowed.	Bows exceeding 1/2-inch in 32-inches are deficiencies.	Builder will repair bowed siding to meet standard. If replacement of siding is required, Builder will match original material as closely as possible. You should be aware that the new finish may not exactly match the original surface texture or color.	Bowed siding due to Your actions or neglect, such as bowing caused by sprinkler system repeatedly wetting siding, is not a deficiency.
Nails have stained siding.	Nail stains exceeding 1/2-inch in length and visible from a distance of 20-feet are deficiencies.	Builder shall correct by either removing stains, painting, or staining the affected area. Builder Shall Match color and finish as closely as possible. Where paint or stain touch up affects the majority of the wall surface, the whole area shall be refinished.	"Natural weathering" or semi-transparent stains are excluded from coverage.
<i>5.6 Roofing</i>			
Roof or flashing leaks.	Roof or flashing leaks that occur under normal weather conditions are deficiencies.	Correct and roof or flashing leaks that are verified to have occurred under normal weather conditions.	Where cause of leaks is determined to result from severe weather conditions such as ice and snow build-up, high winds and driven rains, such leaks are not deficiencies.
Roof shingles or Tiles have blown off.	Shingles/Tiles shall not blow off in winds less than the manufacturer's standards or specifications.	Builder will replace shingles/tiles that blow off in winds less than the manufacturer's standards or specifications only if improper installation is shown to be the cause.	Shingles/tiles that blow off in winds less than the manufacturer's standards or specifications due to a manufacturing defect in the shingles/tiles are the manufacturer's responsibility. Shingles/tiles that blow off in hurricanes, tornadoes, hailstorms, or winds, including gusts greater than 60 miles per hour, are not deficiencies. You should consult shingle manufacturer's warranty for specifications, standards, and manufacturer's warranty responsibility if shingles/tiles blow off in higher wind speeds.
Defective Shingles or Tiles.	NONE. NO COVERAGE.	NONE.	Manufacturing defects in shingles/tiles are not covered under the Limited Warranty. You should consult manufacturer's warranty for specifications, standards, and manufacturer's warranty responsibility.
Standing water on built-up roofs.	Water shall drain from a flat or low-pitched roof within 24-hours of a rainfall.	Builder will take corrective action to assure proper drainage of the roof.	Minor ponding or standing of water is not considered a deficiency.
<i>5.7 Sheet Metal</i>			
Gutters and downspouts leak.	Gutters and downspouts that leak are deficiencies.	Repair leaks in gutters and downspouts.	
Water remains in gutters after a rain.	Small amounts of water may remain in some sections of gutter for a short time after a rain. Standing water in gutters shall not exceed 1/2 - inch in depth.	Builder will repair gutters to assure proper drainage.	You are responsible for keeping gutters and downspouts free from debris that would obstruct drainage.

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
6. Doors and Windows			
<i>6.1 Doors: Interior and Exterior</i>			
Warpage of interior or exterior doors.	Interior and exterior doors that warp so as to prevent normal closing and fit are deficiencies. The maximum allowable warpage of an interior door is 1/4-inch when measured from corner to corner.	Repair or replace as may be required. New doors to be refinished to match the original as closely as possible.	
Door binds against jamb or head of frame or does not lock.	Passage doors that do not open and close freely without binding against the doorframe are deficiencies. Lock bolt is to fit the keeper to maintain a closed position.	Adjust door and Keeper to operate freely.	Wood doors may stick during occasional periods of high humidity.
Door panels shrink and expose bare wood.	NONE.	NONE.	Door panels will shrink due to the nature of the material, exposing bare wood at the edges and are not deficiencies.
Door panels split.	Door panels that have split to allow light to be visible through the door are deficiencies.	If light is visible, fill crack and finish panel to match as closely as possible. Correct one time only during the first year of the Limited Warranty coverage.	
Bottom of doors drag on carpet surface.	Where it is understood by Builder and You that carpet is planned to be installed as the floor finish by the Builder, the bottom of the doors which drag on the carpet are deficiencies.	Undercut doors as required.	Where carpet is selected by You having excessive high pile, You are responsible for any additional door undercutting.
Excessive opening at the bottom of the interior doors.	Passage doors from room to room that have openings between the bottom of the door and the floor finish material in excess of 1-12-inches are deficiencies. Closet doors having an opening in excess of 2-inches are deficiencies.	Make necessary adjustment or replace the door to meet the required tolerance.	
<i>6.2 Garage Doors (Attached Garage)</i>			
Garage door fails to operate or fit properly	Garage doors that do not operate and fit the door opening within the manufacturer's installation tolerances are deficiencies. Some entrance of the elements can be expected under heavy weather conditions and is not considered a deficiency.	Make necessary adjustments to meet the manufacturer's installation tolerances.	No adjustment is required when cause is determined to result from anyone but Builder's or Builder's subcontractors' installation of an electric door opener.
<i>6.3 Wood, Plastic, and Metal Windows</i>			
Window is difficult to open or close.	Windows should require no greater operating force than that described in the manufacturer's specifications.	Builder shall correct or repair as required to meet manufacturer's specifications.	

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
Double hung windows do not stay in place when open.	Double hung windows are permitted to move within a two inch tolerance, up or down when put in an open position. Any excessive movement exceeding the tolerance is a deficiency.	Adjust sash balances one time only during the first year of Limited Warranty coverage. Where possible, Builder will instruct You on the method of adjustment for future repair.	
Condensation or frost on window frames and glass.	NONE.	NONE.	Window glass and frames will collect condensation on the frame and glass surface when humidity and temperature differences are present. Condensation is usually the result of temperature/humidity conditions in the Home.
6.4 Hardware			
A doorknob, deadbolt, or lockset does not operate smoothly.	A doorknob, deadbolt, or lockset should not stick or bind during operation.	Builder will adjust, repair, or replace knobs that are not damaged by abuse, one time only during the first year Warranty Term.	
6.5 Storm Doors, Windows and Screens			
Storm Doors, windows and screens do not operate or fit properly	Storm doors, windows and screens, when installed, which do not operate or fit properly to provide the protection for which they are intended, are considered deficiencies.	Builder shall make necessary adjustments for proper fit and operation. Replace when adjustment cannot be made.	Missing screens, rips or gouges in the screen mesh are not covered by this Limited Warranty.
6.6 Weatherstripping and Seals			
Drafts around doors and windows.	Some infiltration is usually noticeable around doors and windows, especially during high winds. No daylight shall be visible around frame when window or exterior door is closed.	Builder shall repair to meet Construction Performance Guidelines.	In high wind areas, You may need to have storm windows and doors installed to eliminate drafts.
6.7 Glass and Glazing			
Clouding and condensation on inside surfaces of insulated glass.	Insulated glass that clouds up or has condensation on the inside surfaces of the glass is a deficiency.	Builder shall replace glass in accordance with window and glass manufacturer's requirements.	Glass breakage is excluded.
7. Finishes			
7.1 Lath and Plaster			
Cracks in Plaster wall and ceiling surfaces.	Hairline cracks are not unusual. Cracks in plaster wall and ceiling surfaces exceeding 1/16-inch in width are deficiencies.	Builder shall repair cracks that are greater than 1/16-inch in width and touch up paint to match as closely as possible, one time only. Such conditions should be reported near the end of the first year of Limited Warranty coverage to allow for normal movement in Home.	

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
<p><i>7.2 Drywall</i> Drywall cracks.</p>	<p>Hairline cracks are not unusual. Cracks in interior gypsum board or other drywall material exceeding 1/16-inch in width are deficiencies.</p>	<p>Builder shall repair cracks that are greater than 1/16-inch in width and touch up paint to match as closely as possible, one time only. Such conditions should be reported near the end of the first year of Limited Warranty coverage to allow for normal movement in Home.</p>	
<p>Nail pops, blisters, or other blemish is visible on finished wall or ceiling.</p>	<p>Nail pops and blisters that are readily visible from a distance of 6 feet under normal lighting conditions are deficiencies.</p>	<p>Builder will repair such blemishes, and touch up paint to match as closely as possible, one time only. Such conditions should be reported near the end of the first year of Limited Warranty coverage to allow for normal settlement of the Home.</p>	<p>Depressions or slight mounds at nail heads are not considered deficiencies. Builder is not responsible for nail pops or blisters that are not visible, such as those covered by wallpaper.</p>
<p>Cracked corner bead, excess joint compound, trowel marks, or blisters in tape joints.</p>	<p>Cracked or exposed corner bead, trowel marks, excess joint compound, or blisters in drywall tape, are deficiencies.</p>	<p>Builder will repair to meet Construction Performance Guidelines, and touch up paint to match as closely as possible, one time only. Such conditions should be reported near the end of the first year of Limited Warranty coverage to allow for normal settlement of the Home.</p>	
<p><i>7.3 Hard Surfaces</i> Flagstone, Marble, Quarry Tile, Slate, or other hard surface flooring is broken or loose.</p>	<p>Tile flagstone, or similar hard surfaced sanitary flooring that cracks or becomes loose is a deficiency. Sub floor and wallboard are required to be structurally sound, rigid, and suitable to receive finish.</p>	<p>Builder shall replace cracked tiles, marble, or stone and re-secure loose tile, marble, or stone flooring.</p>	<p>Cracking and loosening of flooring caused by Your negligence is not a deficiency. Builder is not responsible for color and pattern variations or discontinued patterns of the manufacturer.</p>
<p>Cracks appear in grouting of ceramic tile joints or at junctions with other material such as a bathtub, shower, or countertop.</p>	<p>Cracks in grouting of ceramic tile joints in excess of 1/16-inch are deficiencies. Re-grouting of these cracks is Your maintenance responsibility after the Builder has re-grouted once.</p>	<p>Builder shall repair grouting as necessary one time only within the first year of the Limited Warranty coverage.</p>	<p>Open cracks or loose grouting where the wall surface abuts the flashing lip at the tub, shower basin, or countertop are considered your maintenance and any resultant damage to other finish surfaces due to leaks, etc. are not considered deficiencies.</p>
<p><i>7.4 Resilient Flooring</i> Nail pops appear on the surface of resilient flooring.</p>	<p>Readily apparent nail pops are deficiencies.</p>	<p>Builder shall correct the nail pops that have caused damage to the floor material and repair or replace damaged floor covering in the affected area. Builder is not responsible for discontinued patterns or color variations.</p>	

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
Depressions or ridges appear in the resilient flooring due to sub floor irregularities.	Readily apparent depressions or ridges exceeding 1/8-inch are a deficiency. The ridge or depression measurement is taken as the gap created at one end of a 6-inch straight edge placed over the depression or the ridge with 3-inches on one side of the deficiency held tightly to the floor.	Builder shall take required action to bring the deficiency within acceptable tolerances so as to be not readily visible. Builder is not responsible for discontinued patterns or color variations in the floor covering. Your neglect or abuse, nor installations performed by others.	
Resilient flooring or base loses adhesion.	Resilient flooring or base that lifts, bubbles, or becomes unglued is a deficiency.	Builder shall repair or replace resilient flooring or base as required. Builder is not responsible for discontinued patterns or color variations.	
Seams or shrinkage gaps show at resilient flooring joints.	Gaps in excess of 1/32-inch in width in resilient floor covering joints are deficiencies. Where dissimilar materials abut, a gap in excess of 1/8-inch is a deficiency.	Builder shall Repair or Replace the resilient flooring to meet the Construction Performance Guidelines. Builder is not responsible for discontinued patterns or color variations of floor covering. Proper repair can be affected by sealing gap with seam sealer.	
<p><i>7.5 Finished Wood Flooring</i> Cupping, Open Joints, or separations in wood flooring.</p>	Open joints or separations between floorboards of finished wood flooring shall not exceed 1/8-inch in width. Cups in strip floorboards shall not exceed 1/6-inch in height in a 3 inch maximum distance when measured perpendicular to the length of the board	Builder shall determine the cause and if the result of a deficiency in workmanship or material, correct one time only. For repairable deficiencies, repair cracks by filling and refinishing to match the wood surface as closely as possible. For non- repairable deficiencies, replace and finish affected area to match remaining flooring as closely as possible.	Wood floors are subject to shrinkage and swell due to seasonal variations in the humidity level of Homes. While boards may be installed tight together, gaps or separations may appear during heating seasons or periods of low humidity. Gaps or separations that close during non-heating seasons are not considered deficiencies. You should be familiar with the recommended care and maintenance requirements of their wood floor. Repeated wetting and drying, or wet mopping may damage wood finishes. Dimples or scratches can be caused by moving furniture or dropping heavy objects, and certain high heel style shoes may cause indentations. These conditions are not covered by the Limited Warranty.
<p><i>7.6 Painting</i> Knot and wood stains appear through paint on exterior</p>	Excessive knot and wood stains that bleed through the paint are considered deficiencies.	Builder shall seal affected areas where excessive bleeding of knots and stains appear, one time only during the first Warranty Term. Builder will touch -up paint to match as closely as possible.	

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
Exterior paint or stain peels or deteriorates.	Exterior paints or stains that peel or deteriorate during the first year of ownership are deficiencies.	Builder shall properly prepare and refinish affected areas, matching color as closely as possible. Where finish repairs affect the majority of the surface areas, the whole area should be refinished. The Limited Warranty on the newly repainted surfaces will not extend beyond the original Warranty Term.	Fading, however, is normal and subject to the orientation of painted surfaces to the climactic conditions which may prevail in the area. Fading is not a deficiency.
Painting required as corollary repair because of other work.	Necessary repair of a painted surface under this Limited Warranty is to be refinished to match surrounding areas as closely as possible.	Builder shall refinish repaired areas to meet the standard as required.	
Mildew or fungus forms on painted or factory finished surfaces.	NONE. NO COVERAGE.	NONE.	Mildew or Fungus that forms on a painted or factory finished surface when the surface is subject to various exposures (e.g.: Ocean, lake, riverfront, heavily wooded areas or mountains) is not a deficiency.
Deterioration of varnish or lacquer finishes.	Natural finish on interior woodwork that deteriorates during the first year of Limited Warranty coverage is a deficiency.	Builder shall refinish affected areas of natural finished interior woodwork, matching the color as closely as possible.	Varnish-type finishes used on exterior surfaces will deteriorate rapidly and are not covered by the Limited Warranty.
Interior paint coverage.	Wall, ceiling, and trim surfaces that are painted shall not show through new paint when viewed from a distance of 6-feet under normal lighting conditions.	Builder shall repaint wall, ceiling or trim surfaces where inadequate paint has been applied. Where the majority of the wall or ceiling surface is affected the entire area will be painted from break line to break line. Builder is not required to repaint an entire room unless all walls and ceiling have been affected.	
Paint splatters and smears on finish surfaces.	Paint splatters on walls, woodwork, or other surfaces which re excessive, shall not be readily visible when viewed from a distance of 6-feet under normal lighting conditions.	Builder shall remove paint splatters without affecting the finish of the material, or replace the damaged surface if paint cannot be removed.	Minor paint splatter and smears on impervious surfaces that can be easily removed by normal cleaning methods are considered to be Your maintenance and are not deficiencies.
<i>7.7 Wall Covering</i> Peeling of wall covering installed by Builder.	Peeling of wall covering is a deficiency, unless it is due to Your abuse or negligence.	Builder shall repair or replace defective wall covering.	Wallpaper applied in high moisture areas is exempt from this Guideline because the problem results from conditions beyond the builder's control.
Pattern in wall covering is mismatched at the edges.	Pattern in wall covering shall match at the edges.	Builder shall remove mismatched wall covering and replace. Builder is not responsible for discontinued or variations in color.	Defects in the wall covering patterns are the manufacturer's responsibility, and excluded from Limited Warranty coverage.
Lumps and ridges and nail pops in wallboard that appear after the Homeowner has wall covering installed by others.	NONE. NO COVERAGE.	NONE.	You shall insure that the surface to receive wall covering is suitable and assumes full responsibility should lumps, ridges, and nail pops occur at a later date.

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
<p><i>7.8 Carpeting</i> Carpet does not meet at the seams.</p>	<p>It is not unusual for carpet seams to show. However, a visible gap or overlapping at the seam due to improper installation is a deficiency.</p>	<p>Builder shall correct to eliminate visible gap or overlapping at the seam.</p>	<p>Carpet material is not covered under the Warranty.</p>
<p>Color Variations in Carpet.</p>	<p>NONE. NO COVERAGE.</p>	<p>NONE.</p>	<p>Colors may vary by dye lot, and from one end to another in the same roll. Side to side shading may show at most if not all seams, even where the same dye lot is used. Carpet material is not covered under the Limited Warranty. You should consult carpet manufacturer's warranty for specifications, standards, and manufacturer's warranty responsibility for color variations.</p>
<p>Carpeting loosens, or the carpet stretches.</p>	<p>When stretched and secured properly, wall-to-wall carpeting installed as the primary floor covering shall not come up, loosen, or separate from the points of attachment.</p>	<p>Builder will re-stretch or re-secure carpeting to meet Construction Performance Guidelines one time only during the first year of Limited Warranty coverage.</p>	
<p>8. Specialties</p>			
<p><i>8.1 Fireplaces</i></p>			
<p>Fireplace or chimney does not draw properly causing smoke to enter home.</p>	<p>A properly designed and constructed fireplace or chimney shall function correctly. High winds can cause temporary negative or down drafts. Negative drafts can also be caused by obstructions such as tree branches, steep hillsides, adjoining homes, and interior furnaces. In some cases, it may be necessary to open a window slightly to create an effective draft. Since negative draft conditions could be temporary, it is necessary for the homeowner to substantiate the problems to the Builder by constructing a fire so the condition can be observed.</p>	<p>When determined the malfunction is based upon improper construction of the fireplace, the Builder shall take the necessary steps to correct the problem, one time only during the first year Warranty Term.</p>	<p>When it is determined that the fireplace is properly designed and constructed, but still malfunctions due to natural causes beyond Builder's control, Builder is not responsible.</p>
<p>Chimney separation from structure to which it is attached.</p>	<p>Newly built fireplaces will often incur slight amounts of separation. Separation that exceeds 1/2-inch from the main structure in any 10-foot vertical measurement is a deficiency.</p>	<p>Builder shall correct. Caulking or grouting is acceptable unless the cause of the separation is due to structural failure of the chimney foundation. In that case, caulking is unacceptable.</p>	
<p>Cracks in masonry hearth or facing.</p>	<p>Small hairline cracks in mortar joints resulting from shrinkage are not unusual. Heat and flames from normal fires can cause cracking.</p>	<p>None.</p>	<p>Heat and flames from normal fires can cause cracking of firebrick and mortar joints. This should be expected, and is not covered by the Limited Warranty.</p>

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
9. Cabinets and Vanities			
<i>9.1 Kitchen Cabinets and Vanities</i>			
Kitchen and vanity cabinet doors and drawers bind.	Cabinet doors and drawers shall open and close with reasonable ease.	Builder shall adjust or replace doors and drawers as necessary to meet Construction Performance Guidelines.	
Warping of kitchen and vanity cabinet doors and drawer fronts.	Warpage that exceeds 1/4-inch as measured from the face of the cabinet frame to the furthestmost point of warpage on the drawer or door front in a closed position is a deficiency.	Builder shall correct or replace door or drawer front as required.	
Gaps between cabinets, ceiling and walls.	Countertops, splash boards, base and wall cabinets are to be securely mounted. Gaps in excess of 1/4-inch between wall and ceiling surfaces are a deficiency.	Builder shall make necessary adjustment of cabinets and countertop or close gap by means of molding suitable to match the cabinet or countertops finish, or as closely as possible; or other acceptable means.	
<i>9.2 Countertops</i>			
Surface cracks and delaminations in high pressure laminate of vanity and kitchen cabinet countertops.	Countertops fabricated with high pressure laminate coverings that delaminate or have surface cracks or joints exceeding 1/16-inch between sheets are considered deficiencies.	Builder shall repair or replace laminated surface covering having cracks or joints exceeding the allowable width.	
10. Mechanical			
<i>10.1 Plumbing</i>			
Faucet or valve leak.	A valve or faucet leak due to material or workmanship is a deficiency and is covered only during the first year of the Warranty.	Builder shall repair or replace the leaking faucet or valve.	Leakage caused by worn or defective washers or seals are Your maintenance item.
Defective plumbing fixtures, appliances or trim fittings.	Fixtures, appliances, or fittings shall comply with their manufacturer's standards as to use and operation.	NONE.	Defective plumbing fixtures, appliances, and trim fittings are covered under their manufacturer's warranty.
<i>10.2 Water Supply</i>			
Staining of plumbing fixtures due to high iron, manganese, or other mineral content in water.	NONE. NO COVERAGE.	NONE. High iron and manganese content in the water supply system will cause staining of plumbing fixtures.	Maintenance and treatment of the water is Your responsibility.
Noisy water pipes.	Some noise can be expected from the water pipe system, due to the flow of water. However, the supply pipes should not make the pounding noise called "water hammer". "Water hammer" is a deficiency covered only during the first year of the Warranty.	Builder shall correct to eliminate "water hammer".	Noises due to water flow and pipe expansion are not considered deficiencies.

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
<p>10.3 Heating and Air Conditioning</p> <p>Inadequate heat.</p>	<p>A heating system shall be capable of producing an inside temperature of at least 70-degrees Fahrenheit as measured in the center of the room at a height of five feet above the floor under local outdoor winter design conditions. NOTE FOR HEATING: There may be periods when the outdoor temperature falls below the design temperature, thereby lowering the temperature in a Home.</p>	<p>Builder shall correct the heating system as required to provide the required temperatures if a deficiency exists.</p>	<p>Orientation of Home and location of room will also provide a temperature differential, especially when the heating system is controlled by a single thermostat for one or more floor levels. You are responsible for balancing dampers and registers and for making other necessary minor adjustments.</p>
<p>Inadequate cooling.</p>	<p>When air conditioning is provided, the cooling system is to be capable of maintaining a temperature of 78-degrees Fahrenheit as measured in the center of each room at a height of five feet above the floor, under local outdoor summer design conditions. NOTE FOR AIR CONDITIONING: In the case of outside temperatures exceeding 95-degrees Fahrenheit, the system shall keep the inside temperature 15-degrees cooler than the outside temperature. National, state, or local requirements shall supersede this guideline where such requirements have been adopted by the local governing agency.</p>	<p>Correct cooling system to meet the Construction Performance Guidelines during the first year of the Limited Warranty coverage.</p>	<p>Orientation of Home and location of room will also provide a temperature differential, especially when the air-conditioning system is controlled by a single thermostat for one or more levels. You are responsible for balancing dampers and registers and for making other necessary minor adjustments.</p>
<p>Ductwork and heating piping not insulated in un-insulated area.</p>	<p>Ductwork and heating pipes that are run in un-insulated crawl spaces, garages or attics are to be insulated. Basements are not "un-insulated areas", and no insulation is required.</p>	<p>Builder shall install required insulation.</p>	
<p>Condensate lines clog up.</p>	<p>NONE. NO COVERAGE.</p>	<p>Builder shall provide clean and unobstructed lines on Effective Date of Warranty.</p>	<p>Condensate lines will clog under normal conditions. You are responsible for continued operation of drain lines.</p>
<p>Improper mechanical operation of evaporative cooling system.</p>	<p>Equipment that does not function properly at temperature standard set is a deficiency.</p>	<p>Builder shall correct and adjust so that blower and water system operate as designed during the first year of Limited Warranty coverage.</p>	
<p>Ductwork makes noises.</p>	<p>NONE. NO COVERAGE.</p>	<p>NONE.</p>	<p>When metal is heated, it expands, and when cooled, it contracts. The resulting "ticking" or "crackling" sounds generally are to be expected and are not deficiencies.</p>
<p>Ductwork makes excessively loud noises known as "oil canning".</p>	<p>The stiffening of the ductwork and the gauge of metal used shall be such that ducts do not "oil can". The booming noise caused by oil canning is a deficiency.</p>	<p>Builder shall take the necessary steps to eliminate noise caused by oil canning.</p>	

DEFICIENCY	Construction Performance Guidelines	Builder/Warrantor Responsibility	Exclusion
11. Electrical Components			
<i>11.1 Switches and Receptacles</i>			
Fuses blow, or circuit breakers kick out.	Fuses and circuit breakers that deactivate under normal usage, when reset or replaced are deficiencies during the first year of Limited Warranty coverage.	Builder shall check all wiring and replace wiring or breaker if it does not perform adequately or is defective.	
Drafts from electrical outlets.	NONE. NO COVERAGE.	NONE.	The electrical junction box on exterior walls may produce a slight air flow whereby the cold air can be drawn through the outlet into a room. This problem is normal in new Home Construction.
Malfunction of electrical outlets switches, or fixtures.	All switches, fixtures and outlets which do not operate as intended are considered deficiencies only during the first year of Limited Warranty coverage.	Builder shall repair or replace defective switches, fixtures and outlets.	
Light fixture tarnishes.	NONE. NO COVERAGE.	NONE.	Finishes on light fixtures may be covered under their manufacturer's warranty.
<i>11.2 Service and Distribution</i>			
Ground fault interrupter trips frequently.	Ground fault interrupters are sensitive safety devices installed in to the electrical system to provide protection against electrical shock. These devices are sensitive and can be tripped very easily. Ground fault outlets that do not operate as intended are considered deficiencies.	Builder shall replace the device if defective during the first year of Limited Warranty Coverage.	